



Industry & Facilities Division
Third Party Inspection Report

| | | |
|---|--|---|
| INSPECTION REPORT No. INS/NR/SHOP-24/590 | | Revision No. 0 |
| <input type="checkbox"/> Initial <input type="checkbox"/> Interim <input checked="" type="checkbox"/> Final <input type="checkbox"/> Resident | | |
| Inspection requested by: Octal Steel Co., Ltd | | |
| Inspection performed as Recognised Authority: | | <input type="checkbox"/> Yes, :(Recognition) <input checked="" type="checkbox"/> No |
| BV Job Nr: _____ | | |

| |
|---|
| IPO Ref (If applicable): N/A (BV internal P/o) |
| P/o nr: (client to BV) |
| P/o nr:N/A (client to Manufacturer) |
| Previous Inspection (If applicable): N/A (Date) |
| Next Inspection (If applicable): To be confirmed |
| Total No. of Inspection Days: 1 |

| MATERIAL / SUBJECT OF INSPECTION <input type="checkbox"/> Refer to attachment section J instead (Indicate if separate material list is provided in attachment) | ITEM / TAG Nr | QTY As per P/O | QTY Offered for inspection |
|---|----------------------|--------------------------|--------------------------------------|
| SMLS PIPE 6" SCH80 3M, X60Q PLS2, API SPEC 5L | 1 | 15 PCS | 15 PCS |
| SMLS PIPE 6" SCH80 2M, X60Q PLS2, API SPEC 5L | 2 | 8 PCS | 8 PCS |
| SMLS PIPE 6" SCH80 1M, X60Q PLS2, API SPEC 5L | 3 | 8 PCS | 8 PCS |

A – INSPECTION RESULT

| | | |
|--|--|--|
| <input type="checkbox"/> Satisfactory (Without comments) | <input checked="" type="checkbox"/> Satisfactory with comments (Any of trailing Punch or Non Conformity items is still open) | <input type="checkbox"/> Not Satisfactory (NCR raised during the inspection) |
|--|--|--|

Inspection Summary: (for details refer to section E)

BV inspector performed the third-party inspection for steel pipes according to reference standard and client requirements.


- Witness hydrostatic test, satisfactory
- Visual inspection, satisfactory with comment

Comment: There are slightly rust could be found on pipe inner surface.

- Dimensional inspection, satisfactory
- Review MTC, satisfactory


The result was acceptable with comment.

| | | |
|----------------------------------|--|--|
| Open Non Conformities: | <input type="checkbox"/> Yes, details in section G | <input checked="" type="checkbox"/> No |
| Open Punch List Items: | <input type="checkbox"/> Yes, details in section H | <input checked="" type="checkbox"/> No |
| Release Note Issued: | <input type="checkbox"/> Yes, number(s): (Release Note number) | <input checked="" type="checkbox"/> No |
| BV Traceability Stamping: | <input type="checkbox"/> Yes, | <input checked="" type="checkbox"/> No |



INSPECTION REPORT No

Revision No. 0



Dimension inspection



Dimension inspection



Dimension inspection



Dimension inspection



Dimension inspection



Dimension inspection